

Flood Risk Management

Section 18 - Schedule

Key Locations and Activities

| REF No' | Location and description of works | Remarks |
|-------------------|--|----------------------------------|
| Nithsdale | | |
| Dumfries | | |
| NFP 10 | Bird sanctuary, Lochside. Screen clearance & inspection | Checked monthly Oct-Apr & in Jun |
| NFP 12 | Maryholm Burn, Sandside. Screen clearance & inspection | Checked monthly Oct-Apr & in Jun |
| NFP 22 | Old Craigs Rd, Craigs burn trash screen. Screen clearance & inspection River Level Monitor | Checked monthly Oct-Apr & in Jun |
| NFP 13 | Mill Burn, Dumfries. NRV inspection | Checked monthly Oct-Apr & in Jun |
| NFP 25 | Holm Avenue, Troqueer. Inspection of outfall with NRV | Checked monthly Oct-Apr & in Jun |
| NFP 14 | Dow Lochar, Logan Barnes. Screen clearance & culvert inspection | Checked monthly Oct-Apr & in Jun |
| Kirkconnel | | |
| NFP 01 | Fauld Head Rd. Grid, culvert & screen clearance & inspection. | Checked monthly Oct-Apr & in Jun |
| NFP 02 | Railway Station. Grids & screen clearance & inspection | Checked monthly Oct-Apr & in Jun |
| Sanquhar | | |
| NFP 04 | Matthews Folly. 2 x screens clearance & inspection | Checked monthly Oct-Apr & in Jun |
| Thornhill | | |
| NFP 05 | Queensberry Brae. Screen clearance & inspection | Checked monthly Oct-Apr & in Jun |
| Kirkbean | | |
| NFP 18 | Kirkbean Burn. Rubble screen clearance & inspection | Checked annually |
| Glencaple | | |
| NFP 16 | Caerlaverock School. Screen clearance & culvert inspection | Checked monthly Oct-Apr & in Jun |
| Nethermill | | |
| NFP 17 | Cumleys Cottage. NRV inspection | Checked monthly Oct-Apr & in Jun |
| Amisfield | | |
| NFP 15 | Amisfield Burn, Moorfoot House. Screen clearance & inspection. | Checked monthly Oct-Apr & in Jun |

Proposed schedule may be subject to variation dependant on external factors such as site specific constraints, operative safety and extreme weather conditions e.g. drought, storms, snow etc.

| | | |
|-------------------------|---|----------------------------------|
| Tynron | | |
| NFP 08 | Auchengibbert Linn. Screen clearance & culvert inspection | Checked monthly Oct-Apr & in Jun |
| Kelloholm | | |
| NFP 03 | Greystone Avenue. Screen clearance & inspection | Checked monthly Oct-Apr & in Jun |
| Dunscore | | |
| NFP 21 | Cannycleugh. Culvert inlet inspection | Checked in Dec & Jun |
| Ruthwell Station | | |
| NFP 23 | Trash screen on Raffles feeder Burn. Screen clearance & inspection | Checked monthly Oct-Apr & in Jun |
| Southerness | | |
| NFP 20 | Golf Course. Screen clearance & inspection | Checked in Dec & Jun |
| Closeburnmill | | |
| NFP 24 | The Auld Smiddy. Screen clearance and inspection | Checked monthly Oct-Apr & in Jun |
| Moniaive | | |
| NFP 26 | Craigdarroch Water & Dalwhat Water Watercourse Inspection | Checked annually |
| Penpont | | |
| NFP 27 | Penpont Burn Watercourse Inspection | Checked annually |